





<b>Vehicle model</b>	LF150 / LF180 / LF210	LF220 / LF250 / LF280 LF230 / LF260 / LF290 / LF320				
<b>Year</b>	(2014>)	(2014>)				
<b>Engine Type</b>	PX-5 112 (Euro 6) PX-5 135 (Euro 6) PX-5 157 (Euro 6)	PX-7 164, 172 (Euro 6) PX-7 186, 194 (Euro 6) PX-7 208, 217 (Euro 6)				
<b>CV(kW) @ rpm</b>	150 (110) @ 2.400 180 (132) @ 2.400 210 (154) @ 2.400	220-230 (162) @ 2.300 250-260 (184) @ 2.300 280-290 (206) @ 2.300 320 (235) @ 2.300				
<b>N. of cylinders/cm3</b>	4 / 4.500	6 / 6.690				
<b>Volts</b>	24	24				
<b>Air Conditioning</b>	Vehicles with or without A/C	Vehicles with or without A/C				
<b>Recommended fittings</b>	Suction	Discharge	Suction	Discharge		
						
<b>Compressors type</b>	TM 21 QP 21	TM 31 QP 31				
<b>Comments</b>	- Can be fit in right hand drive vehicles	- The vehicle must be equipped with special option DAF: "Thermoking Preparation" - Not suitable for vehicles with "Generator Option" - Can be fit in right hand drive vehicles				
<b>Clutch type</b>	Without clutch pulley	Without clutch pulley				
	1B Ø150 3.940 rpm	8PK Ø152 4.237 rpm				
<b>Kit No.</b>	<b>KB16018079</b>	<b>KB17038084</b>				
<b>Last update</b>	2016-01-15	2017-11-15				